



GPSMAP 185 Sounder Addendum

The power/data/transducer cable wiring diagram on page 85 of the GPSMAP 185 Sounder Owner's Manual (part number 190-00158-10), incorrectly indicates that the brown wire on the cable is NMEA Out and the blue wire is NMEA In.

The blue wire is NMEA Out and the brown wire is NMEA In, as indicated in the corrected wiring diagram below.

